
## Gracie Laser Addendum

## Additional Parts & Tools



SBHCS M5 x 16 mm



To attach the laser to the Cutie Frame, first assemble the laser. Attach the assembled laser to the side of the frame top plate with an M5 x 16 mm SBHCS and a 3 mm Allen wrench.

The Grace Company March 23, 2021